
SHEET 1 OF 13



F/G.1.

**SHEET 2 OF 13** 




FIG. 2.

10/518641

**SHEET 3 OF 13** 




FIG.3.

**SHEET 4 OF 13** 






FIG.4.

**SHEET 5 OF 13** 



PPLN. FILING DATE: DECEMBER 20, 2004
TLE: VALVE ASSEMBLY FOR OPENING AND
LOSING A FUEL LINE
VENTOR(S): SEAN LINDEN
TTY. DKT. No.: 032899-018
SHEET 6 0

**SHEET 6 OF 13** 







FIG.11.






FIG.13.

**SHEET 7 OF 13** 




FIG.14.

PPLN. FILING DATE: DECEMBER 20, 2004
TLE: VALVE ASSEMBLY FOR OPENING AND
LOSING A FUEL LINE
VENTOR(S): SEAN LINDEN
TTY. DKT. No.: 032899-018
SHEET 8 0

**SHEET 8 OF 13** 




FIG.15.

ITLE: VALVE ASSEMBLY FOR OPENING AND LOSING A FUEL LINE VENTOR(S): SEAN LINDEN THE DECEMBER 20, 2004

ITLE: VALVE ASSEMBLY FOR OPENING AND LOSING A FUEL LINE VENTOR(S): SEAN LINDEN THE DKT. No.: 032899-018

SHEET 9 0

**SHEET 9 OF 13** 




FIG.16.

PPLN. FILING DATE: DECEMBER 20, 2004
TLE: VALVE ASSEMBLY FOR OPENING AND
LOSING A FUEL LINE
VENTOR(s): SEAN LINDEN
TTY. DKT. No.: 032899-018
SHEET 10 C

**SHEET 10 OF 13** 







FIG.17.

IPPLN. FILING DATE: DECEMBER 20, 2004
ITLE: VALVE ASSEMBLY FOR OPENING AND LOSING A FUEL LINE
IVENTOR(S): SEAN LINDEN
ITTY. DKT. NO.: 032899-018
SHEET 11 C

**SHEET 11 OF 13** 



**SHEET 12 OF 13** 







FIG.20.

IPPLN. FILING DATE: DECEMBER 20, 2004
ITLE: VALVE ASSEMBLY FOR OPENING AND
LOSING A FUEL LINE
IVENTOR(S): SEAN LINDEN
ITTY. DKT. No.: 032899-018
SHEET 13 0

SHEET 13 OF 13







*FIG.23*.